


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-033	Smoke	8/18/2008	ADS/TM	S13WW_002MH	Dry	Yes	1,773.40



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-033	Smoke	8/18/2008	ADS/TM	S13WW_002MH	Dry	Yes	1,773.40

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13WW_013G1	S13WW_013MH	S13WW_003MH	261.4590	8
S13WW_003G1	S13WW_003MH	S13WW_002MH	260.3699	8
S13UU_002G1	S13UU_002MH	S13UU_005MH	310.2018	8
S13WW_014G1	S13WW_014MH	S13WW_013MH	238.9972	8
S13WW_002G1	S13WW_002MH	S13UU_002MH	290.2306	8
S13YY_021G1	S13YY_021MH	S13WW_014MH	200.2759	8
S13YY_025G1	S13YY_025DE	S13YY_021MH	211.8653	8

Observations & Photos

Obs_ID S1028-033-OB01

Address 3421 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13UU_002MH

Comments Smoke from cleanout in front yard. 3421 Wabash Ave.



Picture \S1028-033-OB01-P01.jpg

Comments Front of house, 3421 Wabash Ave.

Obs_ID S1028-033-OB02

Address 3423 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13UU_002MH

Comments Smoke from cleanout in front yard. 3423 Wabash Ave.



Picture \S1028-033-OB02-P01.jpg

Comments Front of house, 3423 Wabash Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-033	Smoke	8/18/2008	ADS/TM	S13WW_002MH	Dry	Yes	1,773.40

Obs_ID S1028-033-OB03

Address 3515 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_003MH

Comments Smoke from cleanout in front yard. 3515 Wabash Ave.



Picture \S1028-033-OB03-P01.jpg

Comments Front of house, 3515 Wabash Ave.

Obs_ID S1028-033-OB04

Address 3517 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_003MH

Comments Smoke from cleanout in front yard. 3517 Wabash Ave.



Picture \S1028-033-OB04-P01.jpg

Comments Front of house, 3517 Wabash Ave.

Obs_ID S1028-033-OB05

Address 3519 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_003MH

Comments Smoke from cleanout in front yard. 3519 Wabash Ave.



Picture \S1028-033-OB05-P01.jpg

Comments Front of house, 3519 Wabash Ave.

Obs_ID S1028-033-OB06

Address 3521 Wabash Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_003MH

Comments Smoke from cleanout in front yard. 3521 Wabash Ave.



Picture \S1028-033-OB06-P01.jpg

Comments Front of house, 3521 Wabash Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-033	Smoke	8/18/2008	ADS/TM	S13WW_002MH	Dry	Yes	1,773.40

Obs_ID S1028-033-OB07

Address 3523 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_003MH

Comments Smoke from cleanout in front yard. 3523 Wabash Ave.



Picture \S1028-033-OB07-P01.jpg

Comments Front of house, 3523 Wabash Ave.

Obs_ID S1028-033-OB08

Address 3641 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13WW_014MH

Comments Smoke from cleanout in front yard. 3641 Wabash Ave.



Picture \S1028-033-OB08-P01.jpg

Comments Front of house, 3641 Wabash Ave.

Obs_ID S1028-033-OB09

Address 3659 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13YY_021MH

Comments Smoke from cleanout in front yard. 3659 Wabash Ave.



Picture \S1028-033-OB09-P01.jpg

Comments Front of house, 3659 Wabash Ave.

